

ERA24LA020

INVESTIGATION PHOTOGRAPHS



Figure 1: Overview of the airplane at the accident site with a collapsed nose landing gear (Photo Courtesy of FAA)



Figure 2: View of the collapsed nose landing gear (Photo Courtesy of FAA)




Figure 3: View of the engine compartment. Note the engine mount was substantially damaged. (Photo Courtesy of FAA)



Figure 4: View of tire tracks from the accident airplane, leading off the runway into the grass (Photo Courtesy of FAA)