

ERA24LA022

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Main Wreckage (Courtesy of FAA)**



**Photograph 2 - Right Side of Nose Section (Courtesy of FAA)**



**Photograph 3 - Right Side (Courtesy of FAA)**



**Photograph 4 - Right Wing (Courtesy of FAA)**



**Photograph 5 - Rear View (Courtesy of FAA)**



**Photograph 6 - Left Side (Courtesy of FAA)**



**Photograph 7 - Left Side of Nose Section (Courtesy of FAA)**




**Photograph 8 - Propeller Spinner (Courtesy of FAA)**



**Photograph 9 - Propeller (Courtesy of FAA)**



**Photograph 10 - Cockpit (Courtesy of FAA)**



**Photograph 11 - First Post Accident Sump - Left Side (Courtesy of FAA)**



**Photograph 12 - First Post Accident Sump - Right Side (Courtesy of FAA)**



**Photograph 13 - Fuel Selector**




**Photograph 14 - Second Post Accident Sump - Left Side**



**Photograph 15 - Second Post Accident Sump - Right Side**



**Photograph 16 - Contents of Right Wing Fuel Tanks after Draining**




**Photograph 17 - Contents of Left Wing Fuel Tanks after Draining**





**Photograph 19 - Fuel Strainer Screen**



**Photograph 20 - Fuel Distribution Manifold**



**Photograph 21 - Fuel Distribution Manifold - Positive Reaction for Water**



**Photograph 22 - Water from inside of Fuel Servo**