

ERA24LA023

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of the airplane wreckage (Courtesy of NTSB)



Photograph 2 - Left side of airplane wreckage. (Courtesy of NTSB)



Photograph 3 - Right side of airplane wreckage. (Courtesy of NTSB)



Photograph 4 - Failed carburetor fuel line from (Courtesy of NTSB)