

ERA24LA030

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph Frontal View of the Nearly Fully Submerged Airplane at the Accident Site



**Photograph 2 - FAA Digital Photograph Left Side View of the Airplane At the Accident Site.
Note the damage to the Left Wing**



Photograph 3 - FAA Digital Photograph View Showing the Upper Inboard Portion of the Right Wing and the Full Span of the Upper Portion of the Left Wing. Note the Compression Wrinkles in the Upper Wing Skins of Both Wings



Photograph 4 - FAA Digital Photograph Frontal View Showing the Damage to the Front Portion of the Airplane



Photograph 5 - FAA Digital Photograph View of the Top of the Airplane Following Recovery



**Photograph 6 - FAA Digital Photograph Left Side View of the Airplane Following Recovery.
Note the Extensive Damage to the Left Wing**



**Photograph 7 - FAA Digital Photograph View of the Installed Emergency Locator Transmitter
Note the BNC Antenna Connector Still Attached**



Photograph 8 - FAA Digital Photograph View Showing the Antenna BNC Connector Installed But the 15-Pin D-SUB Connector Separated