


ERA24LA031

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane at the accident site. (Courtesy of FAA)



Photograph 2 - View of damage to the engine mount. (Courtesy of FAA)