

ERA24LA041

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photograph From Airport Manager. View of the Airplane Before Recovery. Note the Airplane's Location in Proximity to the Aiming Point Marking



Photograph 2 - Photograph From Insurance Adjuster. View taken From the Nose Landing Gear Wheel Well Looking aft Showing the Bottom Fuselage Skin Scrape Damage



Photograph 3 - Photograph From Airport Manager. View of the Bottom Wing Skin of the Left Wing. Note the Abrasion Damage in several areas.



Photograph 4 - Photograph From Airport Manager. View of the Bottom Fuselage Skin. Note the Abrasion Damage.