

ERA24LA059

INVESTIGATIVE PHOTOS



Photograph 1 - Main wreckage at salvage company



Photograph 2 - Engine



Photograph 3 - Wings