

ERA24LA061

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Initial damage overview (Courtesy of FAA)



Photograph 2 - Measurement of delamination/disbonding (Courtesy of FAA)