

ERA24LA063

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Right Side Tail Structure Damage (Courtesy of FAA)



Photograph 2 - Left Side Tail Structure Damage (Courtesy of FAA)



Photograph 3 - View of Airplane and Runway (Courtesy of FAA)