

ERA24LA070

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Propeller (Courtesy of FAA)



Photograph 3 - Propeller Tip Curling (Courtesy of FAA)



Photograph 4 - Propeller Gouge Marks in Runway (Courtesy of FAA)



Photograph 5 - Fuel Sample (Courtesy of FAA)



Photograph 6 - Second Fuel Sample (Courtesy of FAA)