

ERA24LA076

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter damage at the accident site. (Courtesy of FAA)



Photograph 2 - Damaged tail boom after recovery. (Courtesy of FAA)