

ERA24LA079

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the main rotor blade (Courtesy of FAA)



Photograph 2 - View of damage to the main rotor blade (Courtesy of FAA)