

ERA24LA081

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph. View Taken near Initial Touchdown Point Showing the Ground Track During the Forced Landing. Airplane is in the Background.



Photograph 2 - FAA Digital Photograph. Right Forward Quartering View of the Airplane at the Accident Site. Note the Lack of Damage to 2 Visible Propeller Blades.



Photograph 3 - FAA Digital Photograph. Right View of Aft Empennage Showing Structural Damage Near Right Horizontal Stabilator.




Photograph 4 - FAA Digital Photograph. Right Side View of the Upper Portion of the Vertical Stabilizer and Rudder. Note the Damage to the Spar of the Rudder.



**Photograph 5 - FAA Digital Photograph. View of a Portion of the Left Horizontal Stabilator.
Note the Extensive Structural Damage**




Photograph 6 - FAA Digital Photograph. View of the Inboard Portion of the Left Wing, and Left Side of the Fuselage. Note the Impact Damage on the Inboard Portion of the Main Fuel Tank.



Photograph 7 - FAA Digital Photograph. View of the Left Main Fuel Tank Which was Nearly Empty of Fuel.



Photograph 8 - FAA Digital Photograph. View of the Lower Wing Skin of the Left Wing Adjacent to the Impact Damage to the Fuel Tank. Note the Absence of Fuel Stains.



Photograph 9 - FAA Digital Photograph. View Showing the Main and Auxiliary Fuel Tank Readings.