

ERA24LA086

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the airplane at the accident site, with the lighting equipment struck, located in the background (Photo Courtesy of FAA)



Photo 2: View of the damaged left wing (Photo Courtesy of FAA)



Photo 3: View of the damaged left wing (Photo Courtesy of FAA)



Photo 4: View of the damaged left wing (Photo Courtesy of FAA)



Photo 5: View of the damaged left wing (Photo Courtesy of FAA)



Photo 6: View of the damaged left wing, internal view. (Photo Courtesy of FAA)