

ERA24LA087

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right damaged wing and spar. (Courtesy of FAA)



Photograph 2 - View of airplane in the security fence. (Courtesy of FAA)



Photograph 3 - View of damaged right wing aft. (Courtesy of FAA)



Photograph 4 - Aft view of airplane in security fence. (Courtesy of FAA)