

ERA24LA089

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft on runway (Courtesy of FAA)



Photograph 2 - Damage to external longerons (Courtesy of FAA)



Photograph 3 - Damage to external longerons (Courtesy of FAA)



Photograph 4 - Damage to external longerons (Courtesy of FAA)