

ERA24LA092

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Resting Position Overview (Courtesy of FAA)



Photograph 2 - Master Cylinder Piston as Removed (Courtesy of FAA)



Photograph 3 - O-ring and Backup Ring (Courtesy of FAA)