

ERA24LA095

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Top of engine



Photograph 2 - No. 4 Main journal, note: blocked oil port



Photograph 3 - No. 4 main journal



Photograph 4 - Parts of No. 4 Rod cap found in sump



Photograph 5 - Hardware from the No. 4 connecting rod