


ERA24LA095


INVESTIGATION PHOTOGRAPHS

DATE 19 <u>90</u>	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
<u>7/27/90</u>	<u>Tach</u>	<u>7030.4</u>	<u>TSMOH: 0.0</u>	Engine overhauled this date in accordance with Federal Aviation - Administration Regulations, Manufacturer's Overhaul Manual - Form #X30039A, Parts Manual - Form #X30040A. New Parts include: hydraulic lifters, rubber hoses, oil seals, gaskets, packings, circlips, lock plates, retaining rings, pistons, piston pins, piston rings, bearing inserts - Mains and Rods (Std.), rubber drive bushings, exhaust valves, guides, seats (as needed), rocker arm shafts, roto-coils, needle bearings, roller bearings, rocker arm bushings, connecting rod bushings, cotter pins, harness, spark plugs, exhaust gaskets, lockwashers, and counter weight bushings. All

Photograph 1 - Engine Overhaul (Courtesy of Owner)



Photograph 2 - Annual inspection, cylinder 1,3,5 replacement (Courtesy of Owner)



Photograph 3 - Annual inspection, Cylinder 2,4,6 replacement (Courtesy of Owner)