



Photo 1 – View of Glider as Found. Note Tow Plane in Background (FAA)



Photo 2 – View from Departure Runway of Glider’s Fractured Tail (FAA)



Photo 3 – View of Fractured TOST Tow Support Mount (FAA)