

ERA24LA101

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of wreckage. (Courtesy of Airport Operations)



Photograph 2 - Left side profile view of wreckage. (Courtesy of Airport Operations)



Photograph 3 - Left side of fuselage damage. Note, snow occurred post-accident. (Courtesy of FAA)



**Photograph 4 - Right profile view of airplane damage. Note, snow occurred post-accident.
(Courtesy of FAA)**



Photograph 5 - Instrument panel. (Courtesy of FAA)