

ERA24LA105

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Right wing damage (Courtesy of FAA)



Photograph 3 - Engine Note: hole in case half (Courtesy of FAA)



Photograph 4 - No. 2 main journal



Photograph 5 - Bearing material



Photograph 6 - Bearing material



Photograph 7 - Bearing Note: alignment hole with Rod slippage.