

ERA24LA111

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at the accident site (Courtesy of FAA)



Photograph 2 - Airplane at accident site (Courtesy of FAA)



Photograph 3 - Photo of the airplane's underside (Courtesy of FAA)



Photograph 4 - Damage to the vertical stabilizer (Courtesy of FAA)



Photograph 5 - Damage to the vertical stabilizer (Courtesy of FAA)