

ERA24LA113

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site (Courtesy of FAA)



Photograph 2 - Impacted runway light location (Courtesy of FAA)



Photograph 3 - Damage to the stabilator (Courtesy of FAA)



Photograph 4 - Crack found in the right-wing structure (Courtesy of FAA)