

ERA24LA117

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane in the Blueberry Field with PVC Piping (Courtesy of FAA)



Photograph 2 - Leading Edge Damage to Left Wing (Courtesy of FAA)



Photograph 3 - Damage to Right Wing (Courtesy of FAA)



Photograph 4 - Fuel Gauges (Courtesy of FAA)