

ERA24LA118

INVESTIGATIVE PHOTOS



Photograph 1 - Tail rotor assembly with fracture tail rotor.



Photograph 2 - Helicopter with displaced skids



Photograph 3 - Fractured tail rotor