

ERA24LA128

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airframe overview



Photograph 2 - Instrument panel overview



Photograph 3 - Broken aileron cable at fuselage



Photograph 4 - Broken aileron cable at fuselage



Photograph 5 - Broken aileron cable



Photograph 6 - Both sides of the broken aileron cable



Photograph 7 - Close up view of broken aileron cable



Photograph 8 - Close up view of broken aileron cable (fuselage side)



Photograph 9 - Close up view of broken aileron cable (aileron side)




Photograph 10 - Left aileron direct cable pulley (lower left fuselage)



Photograph 11 - Left aileron direct cable pulley (lower left fuselage)



Photograph 12 - Close up view of the lower left fuselage aileron pulley



Photograph 13 - Close up view of the lower left fuselage aileron pulley



Photograph 14 - Right direct aileron cable at the lower right fuselage pulley



Photograph 15 - Corrosion and wear on the right direct aileron cable



Photograph 16 - Corrosion and broken strands on the right direct aileron cable



Photograph 17 - Engine overview, right side



Photograph 18 - Engine overview, left side