

ERA24LA129

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the airplane postaccident (Photo Courtesy of FAA)



Photo 2: View of wing strut and wing root damage (Photo Courtesy of FAA)