



Photo 1 – View of Airplane After Recovery (FAA)



Photo 2 – View of Damage to External Longerons (FAA)