

ERA24LA133

INVESTIGATIVE PHOTOS



Photograph 1 - Damaged right wing. (courtesy of FAA)



Photograph 2 - Damaged left wing. (courtesy of FAA)



Photograph 3 -Damage to visual glide slope lights. (courtesy of FAA)