

ERA24LA141


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane suspended in the trees at the accident site. (Courtesy of FAA)



Photograph 2 - Airplane at the accident site suspended in trees. (Courtesy of FAA)




Photograph 3 - Hole in top of engine. (NTSB)



Photograph 4 - Engine, number 6,4,2 side. (NTSB)



Photograph 5 - Remaining piston rods and bushings. (NTSB)



Photograph 6 - Engine, number 1,3,5 side. (NTSB)



Photograph 7 - Bushing pieces discovered in sump. (Courtesy of Continental Engines)