

ERA24LA151


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane on Scene (Courtesy of Owner)



Photograph 2 -Collapsed Gear and Fuselage Damage (Courtesy of Owner)



Photograph 3 - Bent Structure at Main Landing Gear (Courtesy of Owner)