

ERA24LA153

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of gyroplane from front. (Courtesy of FAA)



Photograph 2 - View of gyroplane from left. (Courtesy of FAA)



Photograph 3 - View of gyroplane from right. (Courtesy of FAA)



Photograph 4 - Close-up view of engine. (Courtesy of FAA)



Photograph 5 - View of fence damage and gyroplane debris (Courtesy of FAA)