

ERA24LA163


INVESTIGATION PHOTOGRAPHS




Photograph 1 – Accident site overview



Photograph 2 – Accident site overview




Photograph 3 – Disconnected fuel line found at the accident site (Courtesy of FAA)



Photograph 4 – Four-way distributor fitting




Photograph 5 – Disconnected fuel line with clamp installed



Photograph 6 – Disconnected fuel line lined up with the four-way distributor



Photograph 7 – Disconnected fuel line after clamp was moved



Photograph 8 – Engine overview