

ERA24LA164

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Frontal View of the Fuselage Following Recovery (Courtesy of Lycoming)



Photograph 2 - Left Side View of Aft Fuselage. Note large Dent (Courtesy of FAA)



**Photograph 3 - Right Side of Aft Fuselage. Note Compression Wrinkle in Fuselage Skin
(Courtesy of FAA)**



Photograph 4 - Right Forward Quartering View of the Forward Fuselage. Note the Extensive Skin Damage Aft of the Firewall (Courtesy of FAA)



Photograph 5 - Left Side View of the Forward Fuselage. Noted the Extensive Skin Damage Aft of the Firewall (Courtesy of FAA)



Photograph 6 - View of the Disassembled Engine-Driven Fuel Pump Showing the Foreign Object Found Inside the Pump (Courtesy of Lycoming)