

ERA24LA165

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overview of the Airplane Damage Right Side (Courtesy of FAA)




Photograph 2 - Overview of the Airplane Damage Left Side (Courtesy of FAA)




Photograph 3 - Airport Security Camera and Windsock Location



Photograph 4 - Windsock During Initial Touchdown



Photograph 5 - Windsock and Smoke When Airplane Stopped



Photograph 6 - N1861M Approach and Frontier Airlines Departure