

ERA24LA166

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of helicopter after recovery. (Courtesy of FAA)



Photograph 2 - View of tailcone damage. (Courtesy of FAA)



Photograph 3 - View of hole in cockpit window. (Courtesy of FAA)



Photograph 4 - Photo taken during flight of where ditching occurred. (Courtesy of pilot)



Photograph 5 - View of helicopter from front after recovery. (Courtesy of Pilot)



Photograph 6 - View of cockpit after recovery. (Courtesy of pilot)



Photograph 7 - View of lower cockpit area after recovery. (Courtesy of pilot)