

ERA24LA173

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N6300Q Landing After Bird Strike (Courtesy of FAA)



Photograph 2 - Right Wing Damage (Courtesy of FAA)



Photograph 3 - Right Wing Damage (Courtesy of FAA)



Photograph 4 - Right Wing Spar Damage (Courtesy of FAA)