

ERA24LA178

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Digital Photograph From Airplane Owner. Left Side View of the Airplane Following Recovery



Photograph 2 - Digital Photograph From Airplane Owner. Right Side View of the Airplane Following Recovery. Note the Substantial Damage to the Vertical Stabilizer



Photograph 3 - Digital Photograph From Airport Personnel. View of Damaged Right Wing Lift Strut