

ERA24LA179

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane at accident site. (Courtesy of FAA)



Photograph 2 - View of airplane from front at accident site. (Courtesy of FAA)



Photograph 3 - View of fuel selector in OFF position at accident site. (Courtesy of FAA)




Photograph 4 - View of airplane from left at accident site. (Courtesy of FAA)



Photograph 5 - View of airplane from rear at accident site. (Courtesy of FAA)



Photograph 6 - Left wing fuel filler port showing rust.



Photograph 7 - Fuel from left wing (left) and from gascolator and carburetor bowls (right).