

ERA24LA180

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Engine Mount Damage (Courtesy of FAA)



Photograph 2 - Empennage Damage (Courtesy of FAA)



Photograph 3 - Left Wing Damage (Courtesy of FAA)