

ERA24LA181

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane after it was up righted. (Courtesy of FAA)



Photograph 2 - View of damaged vertical stabilizer. (Courtesy of FAA)



Photograph 3 - View of right wing strut damage. (Courtesy of FAA)



Photograph 4 - View of airplane inverted next to runway. (Courtesy of FAA)