

ERA24LA183

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at accident site (Courtesy of pilot)



Photograph 2 - Airplane after recovery from lake (Courtesy of pilot)



Photograph 3 - Bent wing strut (Courtesy of FAA)



Photograph 4 - Fuselage damage (Courtesy of pilot)