

ERA24LA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of wreckage at accident site. (Courtesy of FAA)




Photograph 2 - View of wreckage facing aft. (Courtesy of FAA)




Photograph 3 - Wing Strut connection point (Courtesy of FAA)



Photograph 4 - Wing Attachment point top view. (Courtesy of FAA)



Photograph 5 - Fuselage connection point with bolt shown installed. (Courtesy of FAA)



**Photograph 6 - Wing connection point properly installed - Non-Accident Aircraft Side 1
(Courtesy of FAA)**



**Photograph 7 - Wing connection point properly installed - Non-Accident Aircraft Side 2
(Courtesy of FAA)**



**Photograph 8-Wing Connection Point Properly Installed - Non-Accident Aircraft Side 3
(Courtesy of FAA)**