

ERA24LA192

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph. Right Forward Quartering View of the Airplane Following Recovery. Note Damage to the Right Wingtip.



**Photograph 2 - FAA Digital Photograph. Right Side View of the Airplane Following Recovery.
Note the Damage Aft of the Leading Edge Skin of the Bottom Wing Skin**



**Photograph 3 - FAA Digital Photograph. Aft View of the Inboard Portion of the Right Wing.
Note the Buckling of the Upper Skin of the Wing Near the Wing Root**