

ERA24LA196

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft postaccident (Courtesy of FAA)



Photograph 2 - Aircraft postaccident. Note left wing damage (Courtesy of FAA)



Photograph 3 - Left wing tree impact and damage (Courtesy of FAA)



Photograph 4 - Right wing and wing strut damage (Courtesy of FAA)



Photograph 5 - Left wing and wing strut damage (Courtesy of FAA)