

ERA24LA210

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident damage to airport PAPI light (Courtesy of FAA)



Photograph 2 - Postaccident damage to wing (Courtesy of FAA)



Photograph 3 - Postaccident internal wing damage (Courtesy of FAA)