



Joshua Young
Air Safety Investigator
AS-ERA

Date: 5/5/2025

Subject: ERA24LA211, Mechanic Notice to Owner about TBO

Contact: Bill Turley, Aircraft Engineering, Inc.

Aircraft Engineering was contacted by the IIC via electronic mail on 21 April 2025 and asked the following:

"Was the owner ever notified that his engine was 15 years past the manufacturer's recommended time between overhaul?"

They responded on 22 April 2025 via electronic mail stating the following:

"Yes he was, and he had a new engine on order. We did everything we could to make him understand to wait to get the new engine, he was adamant on getting the airplane back."