

ERA24LA224


INVESTIGATION PHOTOGRAPHS



Photograph 1 - New York State Police Digital Photograph. Right Forward Quartering View of the Airplane At the Accident Site



Photograph 2 - Digital Photograph From Repair Facility. Right Forward Quartering View of the Airplane Following Recovery



Photograph 3 - Digital Photograph From Repair Facility. View Depicting Cracks in the Structural Firewall



Photograph 4 - Digital Photograph From Repair Facility. View Depicting Compression Buckle in Engine Mount Tube Requiring Major Repair/Replacement



Photograph 5 - Digital Photograph From Repair Facility. View Depicting The Outer Portion of the Left Wing. Note the Damage along the Leading Edge and Also Chordwise