

ERA24LA230

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Empennage and wreckage at the site. (Courtesy of FAA)



Photograph 2 - View of fuselage wreckage at the accident site. (Courtesy of FAA)



Photograph 3 - View of wreckage at hangar facility. (NTSB)



Photograph 4 - View of left wing at hangar facility (NTSB)



Photograph 5 - View of propeller assembly and engine on hoist. (NTSB)




Photograph 6 - View of number 2 and 4 side of engine. (NTSB)




Photograph 7 - View of right wing damage at hangar facility. (NTSB)



Photograph 8 - View of number 1 and 3 side of engine on hoist. (NTSB)



Photograph 9 - View of damaged magnetos. (Courtesy of Lycoming)



Photograph 10 - View of spark plugs. (Courtesy of Lycoming)



Photograph 11 - View of removed cylinder assemblies. (NTSB)